



Cavity-Tooling:08W-4

	0.03
	0.02

Optimize the cavity  
(recommended for a  
large flow or low pressure  
drop is required)




General tolerance: ±0.3  
UNIT:mm



Cavity-Tooling:10W-4

	0.03
	0.02

Optimize the cavity  
(recommended for a  
large flow or low pressure  
drop is required)



General tolerance: ±0.3  
UNIT:mm